

These articles and information is brought to you by The 1937 and 1938 Buicks Club. For more information please contact us at:

http://autos.groups.yahoo.com/group/1937and1938Buicks/ or WWW.1937and1938Buicks.com

#### -- Warning Notice --

It the mission and goal of 1937 and 1938 Buicks Club is to provide information, helpful hints, advice, directions and reference information for the repair, maintenance, authentic restoration and knowledge development in regards to 1937 and 1938 Buick's. Content is offered as informational only.

The 1937 and 1938 Buicks Club does not knowingly accept false or misleading content or advertising. Nor does The 1937 and 1938 Buicks Club assume any responsibility for the consequences that may occur should any such material appear.

The 1937 and 1938 Buicks Club does not guarantee the quality of any information which is included in this or any other publication. Under no circumstances shall The 1937 and 1938 Buicks Club be liable for any damages, losses, or injuries resulting from use reliance on the content of this or any other publication. Any reliance on this or any other publication content is at your own risk.

As a precautionary measure, The 1937 and 1938 Buicks Club strongly recommends that you contact a professional mechanic or restoration shop to check your work or answer specific questions.

#### -- Copyright Notice --

All rights reserved. All documents and publications on The 1937 and 1938 Buicks Club web site or that can be down loaded from The 1937 and 1938 Buicks Club web site are protected under both U.S. Federal copyright law and international treaties. No component of this site, including text, images and computer code, may not be reproduced or copied in any form or by any means--electronic, graphic, digital or mechanical, including photocopying or information storage & retrieval systems--without the express prior written permission of The 1937 and 1938 Buicks Club.

VOLUME XVI · NUMBER 6 · JULY / AUGUST 1998



## RENEWAL TIME: RENEWAL TIME:

This is the 6th and last issue of our 1997-1998 publishing year. Most members will need to renew. Check the label on the envelope this Torque Tube came in. If it reads 98 as most do, then it's time to renew! Membership in the 1937-1938 Buick Club is \$34 per year US, \$35 per year in Canada and Mexico and \$40 for everyone else. Overseas surface mail is \$35 per year. Please make your check out to the 1937-1938 Buick Club and send it to:

1937-1938 Buick Club 1005 Rilma Lane Los Altos, CA 94022

For your convenience we have enclosed an addressed envelope for your payment. Thanks.

Our 1997-1998 year has set a new membership record for our Club. We now have 576 paying members compared to 558 last year. Thanks to all the members who introduced new members to our Club.

And in addition, the *Torque Tube* was recently awarded its second *Golden Quill* award by *Old Cars Weekly* as one of the best black and white car club publications.

Terry Sullivan (#1335) recently won a trophy showing his beautiful Corot beige '38 Special 4-Door sedan model 41 (below) at the Hillsborough, Ca. Concourse d'Elegance. Hillsborough, in the San Francisco Bay area, was where Bing Crosby lived. Congratulations Terry. And that's a sharp outfit you've wearing!

Had a phone call from an 88 year old man in Great Falls, MT who is still driving the 1937 Special 4 Door Sedan Model 41 he and his father bought new. He only drives the car during the summer and takes the bus during winter. It's been his only car for over 60 years!





I sent him a copy of the Torque Tube and

hopefully he will join our Club.

This beige '38
Roadmaster sedan
Model 81 belongs
to Andrew Leiser
(#1340) in Davis,
California. Andrew
writes: "My first
memory of Buicks
dates to about
1926 when I was 3
years old. I fell out
the left rear door of

our 1919 touring car (an old open sedan). I learned to drive about 1937 in a '31 Buich 4-door sedan with sidemounts. Currently I have four 'Bet-

ter Built' autos, a '28 Country Club Coupe, the '38 Roadmaster, a '90 Station wagon and a '95 Roadmaster station wagon. Would one say that 'Buicks are in my blood?' Or was it that early fall on my head(?) that has made me Nuts about Buicks."

Regarding the centerfold in the March/April

Goering driving up in a 1938 Roadmaster to be met by Hitler. Long time military collector and author Thomas Wittmann writes: "I believe the occasion here was the arrival of Goering for the signing of the French Capitu-

lation in the Compiegne Forest. This was held on June 21st, 1940 and was the occasion when the French signed over the capitulation of their coun-

try in the same Railroad car in which the W.W.I Armistice was signed. Obviously, the delight on Goering's face reflects this momentous occasion for the Third Reich. The Buick automobiles were probably owned by the French Gov-





## = TORQUE TUBE=

You can now find your '37-'38 Buick Club on the World Wide Web.

http://www.classicar.com/clubs/buick/buick.htm

The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:
The TORQUETUBE
You can reach Harry Logan by

1005 RILMA LANE LOS ALTOS, CA 94022 USA PHONE/FAX (650) 941-4587
or by E-mail: harrylogan@earthlink.net

Art Director......Dug Waggoner, #10 Printer Liai

Printer Liaison......Bill Olson, #427
Printer......Conrads Printing, Lancaster, Ohio

All rights reserved. No part of this reconstition may be a produced in any form without written permission from THE TORQUE TUBE.

ernment as Goering would have come to Paris using his private railroad car and then would have needed transportation to Compiegne. This trip is about two and one-half hours by car."

Mike Maroney (#1226) reports the original

AC 46 spark plug for '38 Buicks is no longer being manufactured. Mike says he now uses the AC R46S with good results. The R means it suppresses radio interference while the S means it has

an extended tip. Mike says the heat range is the same as for the original AC 46. Thanks for the

tip Mike.

The next photo on page 2 shows a blue '38


Roadmaster Phaeton Model 80C belonging to Carl Sable in Big Sandy, TX. He has owned it many years.

This cream '37
Special coupe
(above) was
owned by an
American serviceman stationed in

Japan. He sold it and it was recently imported into New Zealand. This car together with *Cliff Humphries* (#747) red '37 Special coupe (*middle*) are the only two '37 or '38 coupes I know of in

New Zealand.

Gene McCoy (#573) in Floral Park,NY writes: "When it comes to getting the best service and used parts for our cars, you need look no further than our own Dave Tacheny (#997). He is most efficient and more importantly honest."



a timely manner, and was always honest in our transactions."

Steve King (#776) in Indiana requests information from members who have put radial tires on a '37 or '38 Buick. If so,

any special wheel preparations? And how did it work? You can reach Steve at (317) 881-8303.

Many of our members have used a company called UVIRA in Merlin, OR. to restore their head-

light reflectors. UVIRA is still in business, but they no longer do headlight reflectors. They told me to contact Vintage Lamp Repair, also in Merlin, OR. Well, I sent a pair of reflectors over a year ago. After

many letters and phone calls, I finally got them back unfinished. So think twice before using Vintage Lamp Repair! I'll probably have my reflectors re-silvered. One company that does this is

Steve's Auto Restorations, 4440 SE 174th, Portland, OR 97236-1381. Their phone number is (503) 665-2222.


This photo (left) of a '38 Buick was once owned by Bob Miller in Pennsylvania. The photo was taken in 1951 when he was a teenager.





The car has a sealed beam headlight conversion, sharkstooth grill guard, blackwall tires and the

running board trim strip is missing. Bob says that he has owned many Buicks over the years. We met while on a W.W.II history tour in Europe last May. Bob and his wife now live in Beverly Hills, Florida.



In keeping

with our continual search for '37-'38 related historical material, this next photo (top) shows a '38 Roadmaster in the Soviet Union during W.W.II. It appeared in a new book called "Operation Barbarossa".

That was the German code name for the invasion in June, 1941. The Roadmaster belonged

to Italian General Messe. Note the turn signal arm on the cowl beltline trim strip, the General's flag by the headlight, the blacked-out headlight and the wood sticks to help the car if it got stuck in the mud. The book incorrectly

calls this car a Packard.

This is my Sudan (light) blue 1937 Century Sport Coupe Model 66S (middle). It's parked next to a house built in 1900. It has the accessory cen-


ter sharkstooth grille guard and fog lights. The car is registered with 1937 California license plates. There is also a license plate holder on right side of the car. It has a "Buick Century" sign. 1 use this to help

prevent rocks from flying up and chipping the fenders. Chipped front fenders are a very com-

mon problem, but the two license plates help shield the fenders from flying rocks. They act as stone guards, helping to reduce the number of fender chips.

This bottom photo appeared in the Los Angeles

Times along with a long article about Uruguay as a treasure throve of ancient autos. Some automobiles that would be at in US museums are commonplace on the roads of Uruguay. The 1938 Buick coupe is but one example. Thanks to *Hal Durian* (#818) in Southern California for sharing this information.



These two '38
Buick Special 4Door Sedans are
awaiting rescue in
a shed at Graveyard II Auto Parts,
3383 Kuhn Rd.,
Coldwater, Ohio
45828. Phone
(419) 586-1367.
The photo (top of
page 5) is from
Cars & Parts

magazine. If you'd like to subscribe to this fine car hobby magazine contact Customer Service at 1-800-448-361, or visit their web site at: www.carsandparts.com or buy it at your local

full service magazine stand.

This 1937 photo (middle of page 5) shows world heavyweight boxing champion James J. Braddock at his training camp preparing to defend his title against Joe Lewis.



Braddock, already the owner of a Roadmaster, is shown taking delivery of a new Buick Century. (Note the ivory colored steering wheel. Most1938 Centurys came with a mahogany colored wheel). On June 22, 1937 in Chicago, Joe Lewis de-

feated Jim Bradock for the heavyweight title.

ters for helping to make this Meet such a success." Jim Knox (#1342) in Palmdale, CA (bottom) found this '37 Century Sedan while driving his

Greg Field (BCA #1) was selling some parts at the Nationals. He had two NOS 1938 BUICK 8 trunk badges. The paint was translucent red. This color was also used on the '38 front bumper badge except for the "8" which was black. Keith Korbut (#1025) reports Tamaya Translucent Red model paint works well.

Ron Stimson (#939) in Ohio reports his 1937 Special Convertible Coupe had it's original in-

terior when he bought it. It had leather seats and arm rests with everything else leatherette (vinyl).

Charlie Ross (#1015), the Director of the Minute Man Chapter (MMC) of the BCA that put on the National Meet in Danvers, MA in July writes: "I would like to thank every one of you

big rig (truck) through Colorado. He saw it was for sale, but passed it by. But he kept thinking about the car and finally returned and purchased it. His son presented him with 28 Torque Tube back issues, so Jim is reading them to help restore his

who came to our

National Meet.

Without your pres-

ence there would

have been no rea-

son to hold the

Meet, I would also

like to thank all the

MMC members

and the members

of our Sister Chap-

This edition of the Torque Tube features '37-'38 McLaughlin-Buicks. You'll find several articles

plus the front and back covers on these Canadian built Buicks. We have 25 members who own

> McLaughlin Buicks.

Again a reminder, most members subscriptions expire with this issue. If your mailing labels reads '98, you will need to renew now! Thank You.



## (Cover Cars)

Depending on the weather in your location, this time of year, our cover photo of a rain spattered 1938 McLaughlin-Buick front bumper badge just might give you some cool relief. It must have been a difficult task to fit the 10 letters in McLaughlin with the 5 letters of BUICK. Today, most Canadians are surprised to see the McLaughlin-Buick name badges as they haven't been used for over 50 years. Thanks to **Bob Ward** (#114) in Ontario, Canada for taking this photo. This ad for a 1937 McLaughlin-Buick, on our back cover, is interesting because even though it is supposed to be a Canadian Buick, it has American hubcaps, wheels and emblems. I guess there wasn't enough money in the budget to make separate ads for the small Canadian market. Thanks to **Richard Parkes** (#169) for sharing this ad.

## CANADIAN BUICKS

#### A McLaughlin-Buick Primer

By Ross McConnell - Edited from the April, 1987 Torque Tube

The McLaughlin Carriage Company in Oshawa, Ontario, Canada was founded in the 1870's by Robert McLaughlin. They built horse drawn wagons, carriages and sleighs. In the early 1900's they decided to make automobiles. Around 1907, Robert's son Sam reached an agreement with Billy Durant to use Buick engines

in their cars. This was the forerunner of McLaughlin-Buick, which eventually became General Motors of Canada at his death in 1972 at the age of 100.

Canadian-built Buicks
were called McLaughlinBuicks until World War II.
Unlike the Australian
Holden, which had the
steering wheel on the right,
its own body, bumpers and
interior, the McLaughlin cars
resembled US Buicks quite
closely. There were, however,
some differences in the running gear and the series and
model numbers were different.

Today, with Canadian and US built cars traveling freely across the border, it is hard to understand why there was a need for General Motors of Canada. The answer was customs duty. Great Britain had a heavy tariff on imported cars, but those made in the British Commonwealth of nations were exempt; thus most of the Buicks coming to England were

McLaughlins. They were advertised as "Products of the Empire."

So General Motors used McLaughlin's large plant in Oshawa to supply the Canadian market as well as the British Empire with General Motors Products of all types except Cadillac.

The Buick was Sam McLaughlin's favorite and the only marque to bear his name. It was more prominently displayed in 1938 than any other year. Most Canadians themselves are always surprised to see the McLaughlin-Buick badges, as they disappeared over

50 years ago. When you consider the low vol-



179,000 US Buicks), plus a climate not very friendly to old metal, the weird accessory differences, paint colors and mechanical parts, the restoration of a US Buick is a piece of cake in comparison. I have tried to list the dif-

ferences between the two cars as they appeared in '37 and '38.

#### EXTERIOR TRIM:

The McLaughlin-Buicks had half-moon hubcaps with three ridges around the edge. They were not scalloped like '38 US ones. The front bumper badge and trunk badge had the words McLAUGHLIN-BUICK. The data plate on the firewall reads "Fisher Body of

PAINT COLORS:

Canada."

Black, dark blue, dark green, gray and dark maroon with completely different name designations, but the same DuPont formulas.

Interior dash and window garnish moldings, horizontal wood grain in light walnut on Special only. Other series I believe were similar to US Buicks.

Engine color was Buick Green, but the valve cover and pushrod covers were

black. Interior fabrics seemed to follow US colors and materials.

#### ACCESSORIES:

Electric clock was standard. The radios were the same. If you didn't order a radio US

ume of production (1938-5,081 McLaughlins vs. coverplates were used. Three spoke hard rubber steering wheels were common. Af-

> termarket GM radio mounted on the firewall and connected to dash controls by flexible cables. Heavy duty oil bath air cleaner

on all models shipped West of Ontario. Heater was still an accessory, but standard on all cars.

MECHANICAL: (Electrical) Starter motor and generator manufactured in Canada by McKinnon Industries. Catherines and identified as such.

#### NON-INTERCHANGEABLE CANADIAN/US MECHANICAL PARTS:

· Wheels are Chevrolet truck using 6 studs

with left hand threads on the left side and right hand threads on the right side.

· Support steering knuckles, brake drums, wheel hubs were all Chevrolet truck.

 Differential ring and pinion, axle shafts and gears will not interchange; these parts are probably Chevrolet truck.

As you can see, the differences are far from startling. The casual observer looking at a row of Buicks would not notice the differences unless they looked closely.


KATEST - ZEHERHELDA

For more information contact:


McLaughlin Buick Club of Canada 220 Industrial Parkway South, Unit #6 Aurora, Ontario Canada L4G 3V6

## McLAUGHLIN-BUICK HAS SURFACED

E.W. Scrivener (#1069)-Ontario, Canada




This car was at a farm auction near my home in Ontario. It was advertised as a 1937 Buick-McLachine! When I saw the car, it was obviously a 1938, a McLaughlin-Buick Roadmaster with dual sidemounts. The owner had died in 1959 and his widow parked the car in a shed, never to be driven again.



The 1959 license plate was still on the car. It starts with the numbers 38, the odometer reads 46,238 and it sat for 38 years before I purchased it in 1997! No one at the auction knew the significance of this car and so I became the new owner at very little expense.



However it has suffered due to sitting on a dirt floor in the Canadian weather all these years. Everything appears to be original except the radio. It's an unusual old GM after-market job.



#### The car's firewall data plate reads:

Serial No. 848190131
Engine No. 3417334
Trim No. 242
Paint No. 800
Body Serial No. 35
Model No. 8-48-19

Canadian GM data plates were different from the US The five digits of the Model No. (8-48-19) gives the vital information on the car:

8	Last number in the year of
	production i.e. 1938.

4	iM c	ode f	or	McLau	ghlin-	Buick.
-					0	

8	Direct		le est	
0	FIISU	num	ber	10

19.....Code for a 4 door sedan.

# Brick Stational Sleet

in 1893 and

The meet was held in Danvers, MA. along Boston's North Shore. The weather was good with plenty of sun and blue skies. There were nearly 400 cars registered and almost 700 people for the banquet dinner. There were 3 1937's, 12 1938's and 22 1940's, the largest class.

In addition to the BCA Meet, there were some very interesting nearby places to visit such as Salem, famous for the witch trials back in 1692. About 25 people were hanged for being witches. Salem also has the house that author Nathaniel Hawthorne was born in 1804. He wrote "The House of the Seven Gables" and "The Scarlet Letter."

Other interesting places were Bunker Hill and the nearby USS Constitution, built 200 years ago. It's the oldest commissioned naval vessel in the world. Also there was the destroyer USS Cassin Young, nearly identical to the destroyer I served on during the Korean War. Other interesting towns were Rockport, an artist colony,


Glouchester, Lexington, Concord and Waldon Pond. In Boston, we walked part of the Freedom Trail, a red path painted on the sidewalk. We walked from Boston Common (the first park in America) to the Old North Church, Paul Revere's house and some very old cemeteries with famous deceased inhabitants such as John Hancock, John Adams and Ben Franklin's parents. We passed the historical home where Franklin was born on Milk Street. We also went to St. Stephen's Catholic church where President Kennedy's mother Rose was baptized

mother Rose was baptized had her funeral 103 years later in 1996!

While at the BCA Meet, I purchased several 1937 Buick magazines. This large photo was part of an article on the beautiful, bustling seaport of Glouchester. The memorial was dedicated in 1923 to the memory of over 8,000 Glouchester fishermen who lost their lives at sea during the past 360 years.



Glouchester is near Danvers, so my wife and I visited the seaport and took this photo of me next to the same memorial 61 years after the Buick magazine article was published.




There were twelve 1938's including four convertible coupes, two Specials and two Century's. This is the most '38 Buick's I've ever seen in one place. There were so many that '38's had their own class while the '36's and '37's were in the same class.

Brick Stational Sleet



There were three1937's at the meet, two Century's and one Special convertible coupe Model 46C owned by **Ben Berman** (#579) in Virginia. The two Century's were **Bill McKenney's** (#1126) black Convertible Sedan Model 60C with fender skirts and **Paul Cook's** gray sport coupe. It was unrestored and has been in his family for many years. His mother and father used this car on their honeymoon!



Joe Bettis from Vermont brought two '38 Century Convertible Coupes, one black with sidemounts and one blue with plain fenders.



This unusual '38 was custom bodied in France by coach builder Henri Binder. It was purchased 8 years ago by **J. W. Pascoe** (#881) in Michigan from the estate of Ernest Stern. Mr. Stern brought it to the US from Europe in 1971. It is pictured before restoration on page 170 in George Damman's book "Seventy Years of Buick."

Thanks to all our members who displayed their cars. And to the Minute Man Chapter of the BCA for all their had work putting on such an enjoyable meet. You made a lot of visitors like me very happy.

# 1998 EASTERN CLUB MEET & TOUR

HISTORIC ROSCOE VILLAGE, COSHOCTON, OHIO

By Bill Olson (#427) - Columbus, Ohio

Those who remember the year the Pittsburgh Pirates baseball team won the World Series (and that, I assume, is most of us even though it was some time ago) may also remember Willie Stargell's rellying one "Wa are family."

Stargell's rallying cry: "We are family!"

Well, that could be said as well about the Eastern Club Meet. Each year it's like a grand family reunion. This year, as in the past, many "regulars" attended and some new "cousins" joined us. Moreover, unlike last year, this time "Uncle Clarence" Hoffman made it and was his irrepressible self. The Roscoe Village Inn gave us good service and ex-

Major-domo Olson, using portable bull-horn, tries to line up the cars for photos at the Ohio Central RR.

cellent food, strolling through the

historic town was lots of fun, and the weather was cool.

Touring the Ohio "Amish Country" was a pleasant surprise to many of the participants; several times during the tours I heard over the CB:



A fine line-up of '37 & '38 Buicks at the Ohio Central Railroad in Sugarcreek.

"Gosh, what beautiful countryside." It is beautiful: rolling hills, woods, and well-kept farms. The sight of an Amish farmer working his fields behind a matched pair of Belgian mares seem to restore one's faith in the basic goodness of mankind. The rust belt, urban sprawl, and interstate highway construction (the last an inevitable feature of Ohio summers) seemed a lifetime away.



(continued from page 13)

Our Friday tour was a treat for steam locomotive fans, a group that includes most antique car fans. After a pleasant drive of 45 minutes we arrived at the Ohio Central Railroad "depot" in Sugarcreek. Ohio Central (which is a regional freight hauler) is owned by a "railroad nut" who, in addition to running a business, has preserved several steam locomotives and other stuff.

The railroad runs a daily (except Sunday) "excursion" behind ex-Canadian Pacific No. 1293, a "modern" steamer built in 1948 and still in excellent condition. Through the courtesy of the railroad's personnel, we were allowed to photograph each car with the locomotive as background. And each participant whose car was photographed received a print as a souvenir.

Seen from a distance, steam locomotives don't seem all that big, but park your car next to one and the car instantly looks like a Crosley or a Morris Minor. The train ride, covering only 12 miles (19 km) but lasting an hour, was enlivened by the patter of the conductor, a young man who obviously enjoys his work. He gave us a combination of information on Amish-country life and groan-producing puns. (Curiously, at the 1997 meet we toured another Canadian Pacific survivor, the Great Lakes steamship "Keewatin.")

This little adventure was followed by an excellent lunch at Beachy's Country Chalet, which features hearty Swiss and German specialties and of course, lots of home-made pies. Saturday's tour gave us another scenic drive and a little taste of Amish life. Yoder's Amish Home in Millersburg features two Amish farmhouses, one typical of 19th Century life and one of today, a barn with animals tended by people who value farm animals highly, and informative tour guides. The modern Amish house tour concluded with the opportunity to watch an industrious lady who thinks nothing of turning out hundreds of loaves of home-made bread each week, and the opportunity to fill bags with the results of her labors, as wall as Amish cookies, jams, fudge and other goodies, all at very modes prices.

The crowd then dispersed on several separate mini-tours. One popular destination was Lehmann's Hardware in Kidron, Ohio, which serves the surrounding Amish communities and has some interesting merchandise, to say the least: woodworkers, how about a "scorp" or a "slick" or a very large drawknife?; ladies, how about pots big enough to make lunch for 40 hungry men at a barn-raising? They've got 'em and much more. (Not needing a scorp, or a two-foot wide skillet, or even a kerosene lamp, but not wishing to come away empty-handed, I bought a hat.)

I can't conclude this report without special mention o my dear friend **José Pardo** (#558), who joined us this year with his wife Stella, all the way from South America. José, as some of you know, is the present owner of a '37 Roadmaster



Frank Wrenich's dark gray with red rims 38-41 in front of a 1930's building and Canadian Pacific 1293.

which I once owned and named "Freya," after the Norse goddess of beauty and love. Aptly enough, José has lovingly finished the restoration which I and a few prior owners could never seem to conclude, and the car is now in Cali, Colombia. The Pardo's flew to



Karl Anderson (#47), as usual in a jaunty pose with his 37-46C.


Minnesota, where José added to his collection of '37's by purchasing a nice unrestored coupe, which he drove to Ohio and down to Florida. The coupe ran fine, but highway speeds tended to dislodge junk from the inside of the fuel tank, and José had to stop every 20 miles or so and blow out the fuel line. On one such stop, he had an interesting interview with a state police officer, who seemed to believe José had stolen the car, but finally was persuaded otherwise.

After a while, José got really good at this line clearing, and came through each day's tours with only minor delays. Inasmuch as José is probably the most intrepid antique car driver I've ever known, I'm sure he got safely to Florida. We'll hear the story from him in the next issue.

No matter where we have 'em and what we do, these meets

are always great fun, and this year's was one of our very best. As the chief planner of it, I will take some of the credit for that, but certainly not all. Everywhere we went, we were accommodated with cheerful courtesy; folks in Ohio's "Amish Country" are just plain nice!

**NOTE:** The **1999** Eastern '37-'38 Meet will be held May 19-22 in French Lick, Indiana. This is a 4 day meet with 3 days of touring. We will be staying at the French Lick Springs Resort (\$84/night). More details to follow. Steve King (#776) is organizing this meet.



A line-up of cars at Yoder's Amish Home in Millersburg

#### BUICK

NO PAGES 2

## PARTS RELEASE AND CHANGE NOTICE

NUM	plant of the section of	DESCRIPT	TION		LIST
ROUP	PART	0.0001111			PRICE
		1938 MoLAUGELIF-B	DICK		
	1				
		Owing to the non-interchangesbility of some of manufactured cars and the United States manufactist of units with their corresponding United S which should enable dealers to determine which before disassembly, also, to know how to order not shown in the following list are identical obuilt cars.	tured cars, we have comp tates and Canadian part parts are not interchang these parts when necessar	numbers eable ry. Parts	
		The parts contained in the following list, under number, should be ordered direct from the Jener Oshawa, Ontario, Canada.	r a General Motors of Car al Motors Products of Car	mida part mida, Ltd.,	
	Canadian Part No.			Buick Part No.	
0.386	1791077	Cover, Valve Hocker Arm Cover, Valve Hocker Arm	1938-40 1936-60-80-90	1394374	
0.416	131674 1789254	But, Spark Flug Cover & Valve Rooker Arm Cover Cover, Spark Flug	1939-40	1287779 1290999 1288746	
2,341	1789256 1781201 1791222	Cover, Spark Flug Strap, Battery Ground Strap, Battery Ground Strap, Battery Ground Wire, Battery to Starter Switch Wire, Battery to Starter Switch Fire, Battery to Starter Switch Gas Tank Kyle Bear	38-40-60; 38-80-90 LHD 38-40-60; 38-80-90 LHD	1304770	
2.342	1791653 1791316 1791326	Strap, Bettery Ground Wire, Battery to Starter Switch	1938-80-90 HHD 1938-80-90 LHD 1938-40-60	1303565 1305091 1304763	
3.001	1791578 1791233	Fire, Battery to Starter Switch Gas Tank	1938-80-90 RHD 1938-40-60	1303564 1304144 1304182	
5,386	1791235 1804679 1804693	Gas Tank Axle, Rear Axle, Rear	1938-90 1938-90	1396443	
	1804709 1804710	Axle, Hear	1938-40 1938-60	1396440	
5.420	1804673 1804674	Axle Shaft, Right Axle Shaft, Left	1936-80-90 1936-80-90 1936-40	1396450 1396451 1396406	
	1804701 1804702 1804705	Shaft, Axle, Left	1938-40 1938-60	1396407	
5.447	1804706 905306	Shaft, Axle, Left Bearing, Finion, Front	1939-60 1938-40-60	1396407 905126	
5.453	593064 1804247	Sleeve, Rear Axle Pinion Bearing Look Differential & Gear	1936-40-60 1938-40 1938-90	1303375 1396402 1396423	
5.529	1804677 1804694 1804220*	Differential & Gear	1938-90 1938-40	1396422	
5.536	1804242*	Ring & Pinion	1938-60 1938-40-80	149520	
5.537	472542 1788199	Adjuster, Differential tearing Steel Wheel - Frimed	1938-40 1338-40	1283600 1303945 1293548	
5.809	1788354 1788910	Brake Drum	1938-40 1938-60 1938-40-60	1300706	
5.812	358501 497992 1788376	Bolt, Front Wheel to Hub Bolt, Front Wheel to Hub Cap, Rub	1938-40-60 1938	1292182	
6.020	1791279	Knuckle, Steering, Right Knuckle, Steering, Left	1938-40-60 1938-40-60	1394254	
6.022	1765429 1765429	Nut, Steering Knuckle, Hight Nut, Steering Enuckle, Left	1938-40-60-80 1938-40-60-80	150252	
6.023	1788292 1788293	Support, Steering Knuckle, Right Support, Steering Knuckle, Left	1938-40-60 1938-40-60 1938-40-60	1297864 1297865 231983	
6.024	231983 231997	Sushing, Steering Knuckle Support Bushing, Knuckle Support Lower Arm Shaft	1938-40-60 1938-40-60	1304860 500863	1
6.178 6.203 6.306	500863 231210 1788182	Bushing, Steering Enuckle Fin Fin, Steering Knuckle King Hub & Drum, Front	1938-40-60 1938-40	1286029	
	1788183 1788912	Hub & Drum, Front Bub & Drum, Front Come, Front Wheel Bearing, Inner	1938-40 1938-40-60 1938-40-60	1291516 1297676 909542	
6.314	909532	annal come anna anna anna	The second		
	1	Cont'A.			
		PARTS BOOKS SHOULD BE CHANGED	TO AGREE WITH THIS SHEET		1

# NON-INTERCHANGEARLE



In May, 1938 Buick put out a "Parts Release and Change Notice" which listed all the noninterchangeable parts. The Release states: "Parts not shown in the following list are identical on both Canadian and United States built cars." Thanks to Jerry Barton (#281) in Enumclaw. Washington for sharing this information displayed here on pages 16 & 17.

FORM 8 P. S. 10.03

#### BUICK

#### PARTS RELEASE AND CHANGE NOTICE

EFFECTIVE May 1 1938

GROUP	PART	DESCRI	PTION		PRIC
6.326 6.330 7.422 7.840 9.766	Canadian Part No. 1788234 370262 500429 1791367 1788987 1788988 1791332 1791332	Packing & Retainer, Front Wheel Bearing Cap, Hub Grease Retaining Bumper, Front Spring Lionogram, Front Bumper Ash Receiver, Right Ash Receiver, Left Monogram, Trunk Honogram, Trunk	1938-40-60 1938-40-60 1938-40-60 1938 1938 1938 1938 except BOC-87 1938-BOC-87	Buick Part No. 231713 1286121 231737 1304275 1304270 1304271 1304624 1304654	
		* 1804220 and 1804242 are the drive pinions an assembly with the ring gear.	only. Suick carries these	e parts as	

... PERFORMANCE ... SAFETY Prove la SÛRETÉ...la PERFORMANCE prouvent que CEST ENCORE


IN-BUICK AGAIN for






# RESTORING YOUR HEADLIGHTS


By Harry Logan (#651)-Los Altos, CA




**A.** 1937 and 1938 headlights are nearly identical, so this discussion applies to both. To get at the interior, start by removing the lens. To do this, loosen the screw at the bottom of the stainless bezel. Then remove both the bezel and lens. Remember, the lenses are marked at the bottom "left" and "right", so be sure to reinstall them correctly.




**B.** The main internal difference is the '37 (*left*) and '38 (*right*) have different types of screw mechanisms to adjust the side to side deflection of the beam during headlight alignment.




C. The 1937 bucket (*left*) uses a long screw to push against a round, spring loaded disc to adjust the light. The '38 (*right*) uses a different arrangement to do the same thing. Also note the '37 bucket has two clips (*one shown*) that hold the bucket in the headlight case. You must depress these clips to remove the bucket.




**D.** After removing the lens and stainless bezel, you should see the bucket and reflector inside the case (*left*). To remove the bucket, use a screwdriver to unsnap the 3 long metal tabs around the edge of the bucket. If you have a '37 light, you'll also have to release the two side clips by running a screwdriver through the holes in the top edge of the case and press the clips inward as you remove the bucket.









- **E.** You can see one of the three long clips that holds the bucket in the headlight case. On the left is the metal cork gasket retainer ring. This ring is sometimes missing.
- F. This shows the terminal strip that screws onto the pointed (rear) end of the headlight case. It's where you attach the wiring inside the engine compartment. Also note the cork gasket and it's retainer ring, the clip at the flat bottom of the reflector that is part of the beam tilt mechanism and the three long tabs that hold the bucket in the headlight case. To remove the reflector from the bucket, press in on the reflector using cotton gloves so as not to scratch or leave fingerprints on the reflector. Press in near the metal tab on each side of the reflector.
- **G.** With the reflector pressed inward, use needle nose pliers to grab the clip holding the reflectors. Rotate the clip so it's wide side lines up with the long slit in the tab, then twist and remove. People sometimes lose the factory clips and substitute cotter pins etc., so your buckets may not have these original style clips. You can buy reproduction clips for \$4 for a set of 4 from I & I Reproductions, 15513 Vermont Ave., Paramount, CA 90723. Phone (562) 531-8117. Ask for Part No. HR 13.



• Now the reflector can be removed from the bucket. Note the metal tab that clips to the flat bottom portion of the reflector to tilt the beam. Note the two wire springs that slip over a metal tongue at each side of the bucket. If the bucket is held upside down, they'll fall out. So put them in a safe place for re-assembly. These springs push against the back of the reflector to help hold it in place.




**I.** With the reflector removed, you can clean the bucket and remove any rust. Then spray it to keep it from rusting. The buckets were originally cad plated, but I usually paint mine. If you want the cad look, *Eastwood* sells a Silver Cad paint in an aerosol can. Order No. 1903Z at \$9.00 a can. Phone: 1-800-345-1178 in the US. Note the two wires (for high and low beam) that run through an orange colored original rubber grommet. These grommets are usually in bad shape and should be replaced.




**J.** If you dissemble the tilt adjustment, note that the spring and long clip go inside the bucket. You also get a good view of one of the three long clips that hold the bucket in the headlight case.



Headlight Bulbs used in '37'38 were 2320-L. They were rated at 32-21 candle power with the approxiemite amperes at 5.00-3.50. In a future issue I will write an article on halogen bulbs and how you can adapt them to your '37 or '38 for brighter headlights.




**K.** Close-up view of one of the two springs that press against the back of the reflector inside the bucket. The reflector is held in the bucket by the two small clips.






M. Note the screw at the bottom of the stainless bezel. It holds the bezel to the headlight case. There is a left and right lens and bezel. The bezel screw head should face the outside of the car.



N. The back side of the lens and it's bezel show the lens is held in place with metal clips. The bezel has a metal tab that fits into a slot in the headlight case.

L. Other GM reflectors are nearly identical to the Buick reflector. The only difference between this '38 Chevrolet reflector (*left*) and the Buick (*right*) one is the parking light socket position in the reflector. Chevrolet and Cadallic had the parking light as part of the headlight while Buick had fender parking lights. This is one of the features I like so much on the Buick, the matching parking light and headlight. With Chevrolet, you could purchase an accessory fender parking light at extra cost.



**0.** Here is the freshly restored headlight with everything in it's place. A project such as this gives your car brighter lights as well the satisfaction of a job well done. A good source of headlight parts such as springs, clips etc. is:


Headlight Headquarters

Donald Axelrod 35 Timson Street Lynn, MA 01902

Phone (617) 598-0523



(From United Motors Service Bulletin Dated 3-29-38)
This is a revise from the May/June '98 T/T issue.



## 1938 VACUUM STARTING SWITCH

A quick check of the switch can be made while the unit is on the car. With the engine running, place a finger over the little relief hole in the rim at the *bottom* of the switch diaphragm

cover. (see arrow)

If a suction can be felt or a hissing sound heard, the diaphragm is leaking and the switch should be replaced.


Photo at right shows the configura-

RELIEF HOLE 1

tion of the switch mounted on the carburetor

### **ELECTRIC WINDSHIELD WIPERS**

Butch's Rod Shop in Dayton, Ohio (513-298-3000) sells 2-speed electric wipers for '37 to '48 Buick, Olds and Pontiac. It mounts under the cowl and hooks to the original wiper towers and linkage. A 2-speed wiper switch and wiring is included with the motor. The part number is #9115 and the price is \$170.00. Thanks to Carl Dahl (#868) in Sacramento, CA for sharing this information.



Basil Ounsted (#1346) 3916 Bedford Road Victoria, B.C. Canada V8T 1C5 37-41

John Vurconic (#1347) 802 Barnsdale Rd. Allentown, PA 18103 37-41

Charles Konesky (#1348) 110 Stolle Rd. Elma, NY 14059



George Corse (#1349) 222 Ridgewood Rd. Media, PA 19063 38-61

Jon Hoffman (#1350) 4739 E. Sunrise Dr. Tucson, AZ 85718 Richard Sirianni (#1351) 2880 S.W. 119 Beaverton, OR 97005 37-41

John Ream (#1352) 490 West Main Street Monrovia, IN 46157 37-61

## Parts FOR SALE

• NOS PARTS	
1941-42 dual manifold pieces for SMALL SERIES engines	
Intake	
Front Exhaust	
Rods for 1937-1950 series 40 and 1940-1950 series 50	
Have total of 13. Price for entire lot	\$350
• REPRODUCTION PARTS	
1938 Roadmaster Model 81 runningboard cores, metal re	
very good original detail	\$230 pair
All parts plus shipping and handling.	
Bill Rossiter (#947)	
1325 Waterloo Court, Riverside, CA 92506 (909)	
• 1938 PARTS	63.5
BIG SERIES fuel pump	
40 SERIES sedan trunk lid (excellent)	
Rebuilt generator	
80 SERIES rebuilt starter	50
Stainless trim	\$10
Grills, need replating	\$45 set
Ash trays	\$5 each
80 SERIES tire rim	\$20
Steering wheel core	\$25
Headlight bucket stainless trim	\$10 each
Light switch	\$20
Stop light switch	\$5
LARGE SERIES water pump	
Pulley	
Fan blade	
Light switch	
LARGE SERIES rocker cover	
• 1937 PARTS	
Bumper guards	\$10
Parking lights	
Rear springs	
Trunk hold-up arms	
Sun visors	
Bumpers	
Running board brackets	
Trunk lid (40 series sedan)	\$30
Doors (40 series 4 Door sedan)	\$25
Stainless (40 series)	
Tail lights	
Head light bucket trim	

Fan blades	
Escutcheon plates	
40 SERIES window winders	
40 SERIES door handles	510
Radio grille	
Glove box door	
Arm rests	\$5
Dome light, no glass (40 series)	
Headlight switch	\$20
John Baine (#1090)	
RR2, Bradford, Ontario	
CANADA L3Z 2A5 (905) 775-2622	

#### • 1937 PARTS

I have street-rodded a 1937 Buick Special 4-door sedan and have these parts for sale:

- · Complete front end and rear end
- · Rebuilt straight eight engine (46,000 miles) and transmission
- Gauge cluster
- · Radio
- · Heater
- · Clock
- · Wheels and nearly new tires
- · Wiper motor and transmission, newly rebuilt
- · Steering column with key and steering wheel
- Hubcaps and beauty rings
- · Also similar parts from a 1936 Special 4-door sedan

Gene Bowman (#1287)

3560 Ruckerville Road, Winchester, KY 40391

e-mail: MGBOWMAN@MEGINC.COM

Phone: (606) 744-1607

#### 1937 PARTS

1937 CENTURY rear axle with 3.9 ring and pinion gears.

Complete with torque tube ......\$1,000 firm.

Jim Brady (#751)

4826 N. Nashville Ave., Chicago, IL 60656

(773) 775-8910

#### 1938 PARTS

- Rare Fold-Down Rear Trunk Guard. New chrome. TRADE ONLY for front horseshoe
  grille guard and Buick 8 bumper badge in like condition.
- 1937-1938 Parts-FREE, you pick up.
- CENTURY non-welled front fenders. 1937 left, 1938 right. Lots of surface rust. Minor rust in bead. Not dented.
- 1938 CENTURY frame, shortened 14 inches in center. Good front and rear sections. (See Torque Tube Vol. XIII, No. 4. page 10).

Lou Wildt (#245), 2210 Trappers Knoll, Batavia, OH 45103-2656 (513) 732-2609

1937 PARTS	
1937 Original Used Hubcaps. Fair to good condition	\$75 set
Steve Nathanson (#656)	
69 Terrace Rd., Walnut Creek, CA 94596	
1938 PARTS	
Running boards for a SPECIAL	\$100
Grille, pitted but not broken	
Rear bumper gravel guard	
Hood ornaments	
Assorted door & window handles	
Head for a SPECIAL	
SPECIAL trunk lid, rough	
Clock	
Front hood hinge	
Joseph Kassakian (#26)	
c/o The Carpet Gallery Inc., 117 Water St. Rt. 206N	Nouton NI 07960
(973) 383-5435	, Newton, NJ 07860
1938 PARTS	
1938 SPECIAL 2-Door Sedan Model 44 body shell plus	both doors and trunk lid.
Rady in starage in Onings Illinois	\$750 or b.o.
body in storage in Quincy, illinois	
John Harter (#949)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673	(949) 492-7674
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	\$8
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	\$8 \$20 each \$15-\$25
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	\$8 \$20 each \$15-\$25
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	\$8 \$20 each \$15-\$25 \$2
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	
John Harter (#949) 157 Mira Velero, San Clemente, CA 92673  1937 SPECIAL PARTS Robe rope & escutcheons (pitted)	\$8

(continued from page 25)
Moldings: Front door (pair), back door (pair), back door to trunk (pair).
Sell only as pairs
Molding: Front door to hood (pair). Sell only as a pair\$20
Hood moldings, sell only as a pair, excellent condition\$100 obc
Engine splash pans\$\$50 pair obc
Moldings, back door, right only\$15
Molding, back door to trunk, right only\$15
Garnish moldings, all plus dashboard. Need restoration. Dash needs minor repairs.
Will consider separating\$125 obo
Door sills, original, good usable condition for a 4-Door sedan\$35 obc
Steering wheel center, complete w/emblem\$15
• 1938 CENTURY PARTS
Exhaust Manifold, left & right side, no center section \$25 each
Fan\$10
Pulley
Distributor #663Z 3327 \$30 obc
Firewall ID tag for a 37-61 4-door sedan\$20
Battery cover\$10
Chrome (inside) door trim. Needs repaircal
Wiper motor, stuck\$15
Vacuum starter switch\$25
• 1937 ALL SERIES PARTS
Klaxon trumpet horns, complete with mounting bracket, rare\$75
Parking light, no lenses, complete\$65 pair
Tail lights w/bezels & lenses, complete
<ul> <li>Picnic Set (30's/40's) with 6 cups, 6 plates, 6 forks, 6 knives.</li> </ul>
Green colored with black suitcase type case, with 2 Thermoses \$100
Prices do not cover postage. 20% extra for postage, or actual postage when ordering large order.
All prices are subject to dickering. Will take reasonable offers.
Jerry Root (#422)

71 South Pollard Dr., Fulton, NY 13069 - (315) 593-2346



1991-1992 Volume X - Numbers 1 through 8

- 1992-1993 Volume XI Numbers 2, 4, 5, 6 and 7
- 1993-1994 Volume XII Numbers 2, 4, 5, and 6
- 1994-1995 Volume XIII Numbers 1, 2, 4, 5, and 6
  - 1995-1996 Volume XIV Numbers 3 through 6
  - 1996-1997 Volume XV Numbers 3 through 6

Please make your checks payable to:

The 1937-1938 Buick Club, 1005 Rilma Lane, Los Altos, CA 94022 USA

#### • PARTING 1937 & 1938

The following is just a portion of the parts available. Call with your needs.

a 1027 BARTS	ur needs.
• 1937 PARTS	
Master and DeLuxe heaters	\$75 each
Rear Fenders, 40-60 Series, excellent	\$150 each
SPECIAL grille shell, mint condition	
SPECIAL front fenders, non-welled, excellent.	\$150 each
ROADMASTER rims	\$25 each
ROADMASTER axles	\$100 pair
ROADMASTER front suspension	call with needs
Coupe & 2 Dr. Sedan side stainless, complete sets	\$75
CENTURY brake & clutch pedal assembly	\$35
CENTURY radiator	\$75
SPECIAL radiator	\$75
Rear springs 40 & 60, good condition	\$100 pair
Radio delete plates	\$15
SMALL SERIES throttle linkage	\$25
BIG SERIES rocker assemblies	\$50
Fender lights	\$65 pair
Trunk lights, complete	¢50
Tail lights with lenses, all series	\$50 main
Wiper transmissions	
Special manifold	530 pair
Throttle cable	
Throttle cable	
SPECIAL colock page	\$100
SPECIAL splash pans	\$40 pair
CENTURY hood	\$200
Headlight switch	\$20
Radio grilles	\$15
Wiper motors	\$15
Trunk hold-up arms	\$20
Sun visors	\$15
Bumpers	\$30 each
Bumper arms	\$15 each
Steering wheel	\$50
40 & 60 running board brackets	\$50 set
Parts radio	\$25
1938 PARIS	
DeLuxe Heaters	\$75 each
Trunk emblem	\$35
40 & 60 sedan trunk lid, no rust	\$75
breatner tubes	\$10 each
Trunk hold-up arms	\$20
7 34Z Starter with solenoid	\$50
Horn button	\$10
SPECIAL hood lettering	
Defroster ducts	¢15 pair
Wiper transmissions	
Rear license plate stand, bracket & light for sedan	
Tail lights, complete	545
Assist straps with screws	

(continued from page 27)	
Throttle cable	
SPECIAL radiator	
Battery tray	\$20
Generator	
SPECIAL manifold, complete	
SPECIAL hood sides & tops	\$25 each
Gas tank door	
Grille, no cracks, minor pitting	\$200
Fender lights	\$100 pair
CENTURY radiator	
SPECIAL coupe window moldings	\$100
Cigarette lighter	
• 1937-1938 PARTS	
SPECIAL running boards, solid cores	\$200 pair
Headlight buckets	
LARGE SERIES air cleaner	\$75
40-60 kingpin sets	\$30
Starter drives	\$20
LARGE SERIES fan belts, new	\$15
Map light switches	
SMALL SERIES spark plug covers	
Rear fender splash aprons	
BIG SERIES manifold ends	
16" beauty rings	
2 Door rear ash trays	
Headlight bezels	
Trunk hinges	
Front arm rests	
40 & 60 rear vent windows, need plating	\$50 pair
Rear view mirrors	\$15
SPECIAL rear motor mounts	
CENTURY rear motor mounts	
40 & 60 4 dr. sedan doors	
Front vent window frames & mechanisms	\$35 each
BIG SERIES fuel pump cores	
Dave Tacheny (#997)	
11949 Oregon Ave. N.	
Champlin, MN 55316	
(612) 427-3460	
• 1937 PARTS-ALL SERIES	
Steering wheel cores	
New voltage regulators, 4 terminal	
Bumper cores, need rechroming (SPECIAL & CENTURY)  • 1937 SPECIAL PARTS	
Transmission, short tailshaft, open driveline floorshift transmission.	
Same bolt pattern as Buic;k Special	\$125
Valve cover, clean, painted	
n III	
Bellhousing	
Bellhousing Head bolt set, used	63

(continued from page 28)
Exhaust center manifold portion with heat riser\$30
8 used domed aluminum pistons, standard bore, useable.
8 rods #31317416B, babbeted
One set of used valve lifters
Water pump pulley\$3
Engine breather tube
Rocker arms, used\$12
Three rims, no tires\$15 each or 3 for \$40
Kingpin set. Thompson 36SN\$30
New pressure plate, 10 inch diameter, Coarse spline disc, new
throwout bearing
1937 CENTURY rear end. Complete including brakes, drums, torque tube.
Has 3.9:1 gears for use in a Special\$375
• 1937 ROADMASTER PARTS
Front seat wood frame, with adjuster mechanism.
Very good wood. No cushion springs\$125
1938 Steering wheel core with good horn button\$50
• 1936 PARTS (possily useable in 1937?)
2 disassembled large series transmissions\$75 each
Good smooth shifting transmission
New Y & Z wiring harness
Large series intake manifold\$25
All prices plus shipping
David Powers (#894)
27732 Paseo Barona,
San Juan Capistrano, CA 92675
(949) 493-1199
(also from same member)

#### INFORMATION WANTED:

Any information on front-rear suspension/engine swap on a late model Corvette into Roadmaster chassis. Anyone have any experience or problems to avoid, or suggestions or better choice? Thanks,

David Powers (#894)



#### WANTED:

Left rear door hinge and hood ornament for a 1936 SPECIAL sedan. Gene Bowman (#1287) 3560 Ruckerville Road Winchester, KY 40391 e-mail: mgbowman@meginc.com Phone: (606) 744-1607

## Gar WANTED

#### **WANTED: 1938**

1938 Buick 4-Door hump back sedan to restore. Contact: Pete Dunkel (614) 891-2639 in Ohio

## Gars FOR SALE

#### FOR SALE: 1937 CENRUTY

4-Door Convertible Sedan Model 60C New chrome, Acuff running boards, all stainless polished. I have all the parts to complete. Runs great. Needs top and interior.

\$17,000 firm Jim Brady (#751) 4826 N. Nashville Ave. Chicago, IL 60656 (773) 775-8910

#### FOR SALE: 1938 SPECIAL

4-Door Trunk Back Sedan Model 41 Sidemounts, new chrome, wiring, tires, upholstery.

All electric's rebuilt. New paint.

Lost interest

88,900

Joseph Kassakian (#26) c/o The Carpet Gallery Inc. 117 Water St. Rt. 206N Newton, NJ 07860 (973) 383-5435

#### FOR SALE: 1938 SPECIAL

4-Door Trunk Back Sedan Model 41 All stock. 75,700 original miles. Black with wide white-wall tires.

Red rims with silver striping.

No rust. The chrome, stainless trim and grille are all outstanding.

Very nice looking '38 Buick. Has won several trophies....... \$10,000 OBO

Paul Dahl

North St. Paul, MN (651) 770-1242 evenings

#### FOR SALE: 1938 SPECIAL

Sport Coupe Model 46S.

Dual sidemounts, Tripp lights, front bumper badge, horseshoe grill guard, groundup restoration. Has won A.A.C.A.1st Jr., 1st Sr., 1st Grand National, and 7 preservation

awards...... \$25,000

Russ Dawson (#504)

Phone: (Florida) (407) 841-8466.

E-mail dawson@purplenet.net

#### FOR SALE: 1938 SPECIAL

4-Door Trunk Back Sedan Model 41 (see photo at right)

Good original condition, very complete. Have original (not reproduction) owners manual, service coupons and records.

Enjoyable driver as is, or would make easy restoration.

Asking....... \$10,000 OBO (also from same member)

#### WANTED:

#### 1937 or 1938 CENTURY

Prefer 4dr trunk sedan, but others considered. Prefer excellent restoration or complete original car with potential for same. Bernard S. Thurman (#1343) 640 Pacheco Street

San Francisco, CA 94116 (415) 731-3414





FRONT FLOORMAT 1937-38 All Models Black or Brown FF-378......\$195.



# **BOB'S**AUTOMOBILIA (805) 434-2963

#### 1937-38 BUICK



DOOR WEATHERSEAL-SPONGE
Glue-in DW-378 \$1.80 ft.
Clip-in DW-80 \$3.25 ft

Clip-in DW-80 \$3.25 ft.
Clips WC-80 \$.75 ea.
DOOR BOTTOM SEAL
Clip Type DW-369 \$2.25 ft

TRUNK SEAL-SEDANS. 1/2" Wide; Ser. 80-90.......TW-371.....\$35.50

Sedans. 3/4" Wide; Ser. 40-60.......TW-371S......\$37.50

TRUNK SEAL For COUPES. 5/8\* x 1\*
Sponge .....TL-369 .................\$2.00 ft.
1/2'x1'x16' TL-1129 ..............\$47.50

PEDAL FLOOR SEALS; All Models \$12.50 pr.

SHIFT BOOT. 1937-38 Series 40 Only!

Black \$ 9.25

Brown \$18.50

Series 80-90 Black ONLY \$ 8.50

DOOR SILLS; Trim To Fit 2-Door \$62/pr. 4Door \$93/set. GLOVE BOXES; \$27. ea.

PARKING LIGHT LENS...... \$18.00 ea

CARB, KITS:CARTER......CK-360C .\$26.00 STROMBERG...... CK-37XS \$26.00

TORQUE BALL SEAL KIT. All Models
TBK-343. .....\$26.00

VISOR "VANITY" MIRROR. VM-379 ..... \$27. ea.

LICENSE PLATE FRAMES. Chromed Brass LF-333P.....\$62. Pair





EXHAUST MANIFOLDS 1937-38 Series 60-80-90 ENDS \$180. CENTER \$182. VALVE BODY \$195.

RUNNING BOARD INSULATORS, 1937-38
All Models, ALL NEW MATERIAL!
4 Needed Per Running Board.
RI-378S Set of 8, \$160.0

RI-378S ......Set of 8 .. \$160.00

DASH GLASS. SILK-SCREENED on
Back of GLASS in COLORS as
Original 1937.....SPEEDO DG-37....\$38.
.......RADIO....RG-37...\$23.
.......CLOCK...CG-37...\$28.
1938....SPEEDO DG-38...\$38.
......RADIO...RG-38...\$23.
..........S23.......\$23.

PLASTIC DASH KNOBS DK-37(38) ..... \$ 6.
PLASTIC DOOR HANDLE and Window
Winder RINGS .HE-37(38) ................ \$ 6.

OUTSIDE DOOR HANDLE CHROME
and RUBBER GROMMETS.

1 FERRULE & 1 GROMMET Per Set.
1937......DGF-296............\$5/Set
1938.....DGF-380......\$5/Set

DOOR FERRULE INSTALATION TOOL. \$20. Refundable if Returned Within 30 Days. DF-TOOL.....\$29.

1938 TRUNK HANDLE/LIGHT MOUNTING SEAL ..... DH-381 ......\$8.95

MOTOR MOUNT, FRONT. All Models ROUND PADS...... SP-338...\$10. pr. MOUNT......MM-347..\$25. ea.

TRUNK HINGES for 40-60. Chrome Plated \$150. pr.

1937 HUB CAPS. All Ser..... HC-37.... \$60. ea. WHEEL Beauty Rings. 15' or 16' ...... \$99./Set of 4 1937 or 38 HOOD ORNAMENT ...... \$85.

SOME OTHER ITEMS WE STOCK; BEARINGS, DECALS, ENGINE PAINT, DECALS, SHOP MANUALS, PARTS BOOKS, BODY BOOKS and MORE SHIPPING; 10%. max.\$9. min. \$4. Prepaid. C.O.D. Add \$5.


BOB'S AUTOMOBILIA BOX 2119 ATASCADERO CA. 93423 TELEPHONE (805) 434-2963 .VISA- MASTERCARD-DISCOVER or C.O.D. CATALOG #45 \$5.00 - PHONE ORDERS - (Write-For Catalog)













I sent him a copy of the Torque Tube and

hopefully he will join our Club.

This beige '38 Roadmaster sedan Model 81 belongs to Andrew Leiser (#1340) in Davis, California. Andrew writes: "My first memory of Buicks dates to about 1926 when I was 3 years old. I fell out the left rear door of

our 1919 touring car (an old open sedan). I learned to drive about 1937 in a '31 Buich 4-door sedan with sidemounts. Currently I have four 'Bet-

ter Built' autos, a '28 Country Club Coupe, the '38 Roadmaster, a '90 Station wagon and a '95 Roadmaster station wagon. Would one say that 'Buicks are in my blood?' Or was it that early fall on my head(?) that has made me Nuts about Buicks."

Regarding the centerfold in the March/April

issue showing Goering driving up in a 1938 Roadmaster to be met by Hitler. Long time military collector and author Thomas Wittmann writes: "I believe the occasion here was the arrival of Goering for the signing of the French Capitu-

lation in the Compiegne Forest. This was held on June 21st, 1940 and was the occasion when the French signed over the capitulation of their coun-

try in the same Railroad car in which the W.W.I Armistice was signed. Obviously, the delight on Goering's face reflects this momentous occasion for the Third Reich. The Buick automobiles were probably owned by the French Gov-



## = TORQUE TUBE=

You can now find your '37-'38 Buick Club on the World Wide Web.

http://www.classicar.com/clubs/buick/buick.htm

The TORQUE TUBE is published every two months for the enjoyment of the 1937-1938 Buick Club. Membership dues are \$34.00 per year US, \$35.00 per year Canada or Mexico and \$40.00 per year for all others. All issues mailed First Class and Overseas issues are mailed Air Mail-Printed Matter unless Surface Mail, at \$35.00 per year, is requested. All memberships run September 1 to August 31 of the following year. Persons joining during the year will receive all back issues from September 1. All payments must be in U.S. funds. Please make your check payable to the 1937-1938 Buick Club.

Please send all articles, ads subscriptions and inquires, etc. to:
The TORQUE TUBE
You can reach Harry Logan by

1005 RILMA LANE LOS ALTOS, CA 94022 USA PHONE/FAX (650) 941-4587 or by E-mail: harrylogan@earthlink.net




### Buick...Upholstery and Top Kits 1932/1955

Since 1977 .. Hampton Coach has been producing only the finest quality Interior and Top products available for GM cars. We offer complete interior Kits Seat Upholstery, Tops and related accessories as well as "era" fabric by the yard ...

Inquire Toll Free

1-888-388-8726



6 Chestnut St Tel 978-388-8047



Amesbury, MA Fan 978-388-1113



Restoration and repairs that are correct and authentic. "I know your Buick." Former Director of Long


Island, NY Chapter now has fully equipped shop in North Georgia. Ron Stanger, BCA #21079

Classic Car Works Ltd., 3050 Upper Bethany Rd. Jasper, GA 30143 Phone (770) 735-3945



## onaldson Co.

2533 W. Cypress St. Phoenix, Arizona 85009 (602) 278-4505



Beautifully Recast STEERING WHEELS

Thru 1953 Call or write for brochure



RESTORATION



SERVICES

Running Board / Rocker Moldings

1934 thru 1940

SSAE for Information

**BUICK RESTORATION SERVICES** 

P.O. BOX 442. PERRY.

MICHIGAN

48872



1927

1953

#### HARNESSES

AUTHENTIC REPRODUCTION WIRING SYSTEMS THRU 1953 HAND CRAFTED WITH THE FINEST MATERIALS EACH SUPPLIED WITH: LIMITED WARRANTY INSTALLATION INSTRUCTIONS SCHEMATICS

ALSO OFFERING: WIRING SUPPLIES CATALOG OR INFORMATION S5



BOX 435 WAYNE, PA. 19087 000

THURS OF A DEANY GOWER

Melauchlin

